


■ - Denotes location of open box of asbestos waste

Job North



Prepared by:



**CROTHERS** Environmental Group, LLC  
29 Duncan Road  
Morrisville, Vermont  
802-888-1936

Waterbury State Office Complex

103 South Main Street - Waterbury, Vermont

"A" Building, 1st floor

*Compliance Inspection Photograph Locations*

Not to scale

December 3, 2013

AA-2